

**ZURUWIFT
WORKS
LTD.**



Kapture[®]

Manual

Scan & Pair



Press the middle button on the sensor to activate all sensors

Scan & Pair

Names of connected sensors will show up on the left side of the list



Scanning

→ Kapture1AB03
KaptureBD643
KaptureAG592
KaptureCE128
KaptureAC498
KaptureAE332
KaptureBQ257
KaptureTK245

Scan

AC – 587 ▾

Head

Pair

Chest

R Upper Arm

R Forearm

R Hand

L Upper Arm

L Forearm

L Hand

BD – 643

AG – 592

CE – 128

AC – 498

AE – 332


BQ – 257

TK – 245

Click the name of each sensor for mapping it to a desired body part




Make sure that all lights on the sensors have turned green before moving to the next step




Wearing


Fit the straps and sensors to the specified positions



Please make sure all the arrows on the sensors are pointing down when you are in a natural standing pose



Body Manager



You can pick a proper body profile from the Body Manager on the upper right corner

You can also key in the value and save it as a custom profile

Calibration

Click on Calibration button and go on with the on-screen instruction that will guide you through the process.

► Calibration can be done while standing or sitting.

The screenshot shows the 'Calibration Guide' interface. On the left, a 3D mannequin is in an 'L Pose' with arms extended forward. A progress bar at the bottom indicates 20% completion. On the right, a sidebar contains a body map, a table of body details, and control buttons. Annotations with orange lines point to various elements:

- Go back to setting (points to the back arrow in the top left of the sidebar)
- Device connection status (points to the body map)
- Body details in use (points to the 'Body Details' section header)
- Once the "Calibration" button is clicked, it will start the process (points to the 'Calibration' button)
- Click the close button to turn off all devices at once (points to the 'Power off' button)
- Enter the value here to open the port (points to the 'Port' input field)

Calibration Guide

STEP 1
L Pose

Please raise your hands forward, palms parallel to the ground, and maintain this position until the progress is completed.

20%

Body Details

Female 150	
Head	15.43
Neck	7.71
Body	50.39
Shoulder Width	29.00
Upper Arm	19.50
Forearm	21.00
Palm	15.50

Buttons: Tips, Calibration, Power off


Deploy: ☐

Port: 2738

Legend:


- Connected (green dot)
- Connecting (yellow dot)
- Disconnect (grey dot)
- Low Battery (red dot)

Body Measurement



How to take accurate body measurements

Use a soft measuring tape or piece of string that can later be measured





Start to use and have fun !